

Steel industry – Bath equipment monitoring



Customer *problem*: strong influence of immersed bearing wear level on coating performance




***V*_{2i} solution:** development of a specific vibration indicator linked to bearing wear



V2i system

- Acquisition
- Recording
- Processing
- Remote access
- Web database

**Customized hardware
& software**



***V*_{2i}**